



**higher education
& training**

Department:
Higher Education and Training
REPUBLIC OF SOUTH AFRICA

MARKING GUIDELINE

NATIONAL CERTIFICATE (VOCATIONAL)

NOVEMBER EXAMINATION

**FITTING AND TURNING
NQF LEVEL 2**

30 NOVEMBER 2015

This marking guideline consists of 5 pages.

QUESTION 1: GRINDING AND SHARPENING

- 1.1 A place for everything and everything in its place. Also refers to the general and routine work done to maintain cleanliness and tightness around the workplace. (2)
- 1.2
- Limits the time spent searching for tools etc
 - Space is saved
 - Injuries are prevented
 - Fire hazards are reduced
 - Improves the working environment and workers' morale
 - It increases production
 - Accidents are kept to a minimum (5 x 1) (5)
- 1.3
- Hardening
 - Tempering
 - Annealing
 - Normalising
 - Case hardening (3 x 1) (3)
- 1.4
- 1.4.1 To correct an 'out-of-round' wheel
- 1.4.2 To restore the wheel's sharpness (2 x 2) (4)
- 1.5
- Loading of the wheel
 - Glazing of the wheel
 - Wheel not running concentrically to the spindle (3)
- 1.6
- Carbon steel
 - High speed steel
 - Tungsten carbide (3)
- [20]**

QUESTION 2: DRILLING MACHINES

- 2.1
- Wear goggles/safety glasses
 - Never try to stop the drill spindle by hand
 - Never leave the machine unattended
 - Clamp the workpiece securely
 - Remove the chuck key before starting the machine
 - Do not make any adjustments/repairs while the machine is running (5)
- 2.2
- A – Taper shank
 B – Body length
 C – Point
 D – Overall length
 E – Helix or rake angle (5)

- 2.3 $D = 20 \text{ mm} = 20/1\,000 = 0,02 \text{ m}$
 $N = 90 \text{ rpm}$
 $S = ? \text{ m/min}$
 $S = \pi \times D \times N$
 $= \pi \times 0,02 \times 90 \sqrt{\sqrt{\quad}}$
 $= \underline{5,655 \text{ m/min}} \sqrt{\sqrt{\quad}}$ (3)
- 2.4
- U-clamp
 - Straight clamp
 - Finger clamp
 - Offset clamp
 - G or C clamp
- (5)
- 2.5
- Extends the life span of the drill
 - Prevents metal from building up on the cutting edges
 - Does not form gummy deposits
 - Non-flammable
- (Any 2 x 1) (2)
[20]

QUESTION 3: HAND THREADING AND REAMING

- 3.1 3.1.1 Internal thread is one which is cut on the inside surface of a hole
eg. a nut
- 3.1.2 Crest is the top part of the thread
- 3.1.3 Root lies at the bottom of the thread; the base where two adjacent
flanks meet
- 3.1.4 Pitch is the distance from one point of a thread to a corresponding
point on the adjacent thread (4 x 2) (4)
- 3.2 Tap drill size = major diameter – pitch
 $= 10 - 1,5 \sqrt{\quad}$
 $= \underline{8,5 \text{ mm}} \sqrt{\quad}$ (2)
[10]

QUESTION 4: KEYS AND FASTENERS

- 4.1
- Rectangular/parallel
 - Feather
 - Taper gib-head
 - Woodruff
- (4)
- 4.2
- $$h = D/6$$
- $$= 36/6\sqrt{}$$
- $$= \underline{6 \text{ mm}}\sqrt{}$$
-
- $$w = D/4$$
- $$= 36/4\sqrt{}$$
- $$= \underline{9 \text{ mm}}\sqrt{}$$
- (4)
- 4.3
- Side milling cutter
 - Slot drill
- (2)
- [10]**

QUESTION 5: CENTRE LATHE

- 5.1
- 1 – Headstock
 - 2 – Carriage
 - 3 – Tailstock
 - 4 – Tool post
 - 5 – Compound slide
 - 6 – Cross slide
 - 7 – Apron
 - 8 – Feed shaft
 - 9 – Lead screw
- (9)
- 5.2
- | ADVANTAGES | DISADVANTAGES |
|--|---|
| <ul style="list-style-type: none"> • Ease of work setting. • A wide range of cylindrical and hexagonal workpieces can be held. • Work can be readily performed on the end face. • Work can be bored. <p style="text-align: right;">(Any 2 x 1)</p> | <ul style="list-style-type: none"> • Accuracy decreases as chuck becomes worn. • Centring accuracy is limited when work is reversed. • Run-out' cannot be corrected. • Only round and hexagonal components can be held. <p style="text-align: right;">(Any 2 x 1)</p> |
- (4)
- 5.3 Supports a workpiece (1)
- 5.4
- Workpieces are easily mounted and removed
 - External turning will be true to internal diameter
 - Setting up is simple, quick and true
 - Can be adapted to suit a large variety of workpieces
- (Any 3 x 1) (3)

5.5 $D = 50 \text{ mm} = 50/1\,000 = 0,05$
 $N = 900 \text{ rpm}$
 $S = \pi \times D \times N$
 $= \pi \times 0,05 \times 900 \sqrt{\sqrt{}}$
 $= \underline{141,372 \text{ m/min} \sqrt{}}$ (3)
[20]

QUESTION 6: MILLING MACHINE

- 6.1
- Machining dovetails, grooves and splines
 - Making spur, bevel and spiral gears
 - Performing drilling, boring and profile cutting operations
 - For making flat surfaces, squaring
 - For mass production of workpieces
- (5)

- 6.2
- Wear goggles/safety glasses
 - Clamp your workpiece securely
 - Never leave the machine unattended
 - Make sure the cutting tool is secured
 - Do not make any adjustments while the machine is running
- (3 x 1) (3)

- 6.3
- Plain horizontal
 - Universal
 - Vertical
 - Turret-type
- (4)

6.4 $S = \pi \times D \times N$
 $N = S / \pi \times D$
 $= 24 / \pi \times 0,025 \sqrt{\sqrt{}}$
 $= \underline{305,577 \text{ r/min} \sqrt{}}$

$f = f_t \times T \times N$
 $= 0,051 \times 4 \times 305,577 \sqrt{\sqrt{}}$
 $= \underline{62,334 \text{ mm/min} \sqrt{}}$ (3 x 2) (6)

- 6.5
- Solid
 - Split
- (2 x 1) (2)
[20]

TOTAL: 100