



higher education & training

Department:
Higher Education and Training
REPUBLIC OF SOUTH AFRICA


MARKING GUIDELINE

NATIONAL CERTIFICATE (VOCATIONAL)

**FITTING AND TURNING
NQF LEVEL 2**

28 November 2023

This marking guideline consists of 5 pages.



Approved 202311 DHET marking

Guide. No amendments or additions

Must be made on this guide.

QUESTION 1

- 1.1 1.1.1 True
- 1.1 1.1.2 True
- 1.1 1.1.3 False
- 1.1 1.1.4 False
- 1.1 1.1.5 False

(5 × 1) (5)

- 1.2 A – Motor
- B – Eye shield/Safety shield
- C – Cover/Guard
- D – Wheel/Grinding wheel/Stone/Grinding stone
- E – Tool rest/rest
- F – ON/OFF Switch

(6 × 1) (6)

- 1.3 D = 200 mm = 0,20 m ✓ (Do not penalise student if didn't convert to m)
- S = 1 670 m/min
- N = ?

$$S = \pi \times D \times N \checkmark$$


$$N = \frac{S}{\pi \times D} \checkmark$$

$$= \frac{1\ 670}{\pi \times 0,20} \checkmark \checkmark$$

$$= 2\ 658\ r/min \checkmark$$

(5)

1.4



(ONE mark for accuracy) (5 + 1)


(6)

NEATNESS

- 1.5
- Straight-flute (parallel) reamer
 - Helical flute reamer
 - Taper reamer
 - Expanding reamer
 - Adjustable reamer
 - Machine reamer
- (Any 3 × 1) (3)
[25]

QUESTION 2

- 2.1
- A – Motor for elevating the arm
 - B – Motor for driving the drill spindle
 - C – Table
 - D – Base
 - E – Column
 - F – Radial arm
- (6 × 1) (6)



(TWO marks for accuracy and neatness) (4 + 2) (6)

- 2.3
- 2.3.1 Dry
 - 2.3.2 Soluble oil
 - 2.3.3 Soluble oil EP (extreme pressure)
- (3 × 1) (3)

- 2.4
- Select the correct size by its number.
 - Remove any burrs and rough edges from the shaft and hub.
 - Thoroughly clean the shaft and hub.
 - Fit the key by gently tapping it with a soft mallet.
- (Any relevant answers) (4)

- 2.5
- External circlip
 - Internal circlip
- (2 + 2) (4)

- 2.6
- A Helicoil is a spring which has an external and internal thread shape.
- (2)
[25]

QUESTION 3

- 3.1
- Parallel turning
 - Taper turning
 - Screw threads cutting
 - Boring
 - Drilling
 - Parting
 - Knurling
 - Facing
 - Chamfering
- (Any other relevant answers) (Any 5 × 1) (5)
- 3.2
- Insert the cutting tool in the tool post holder and tighten it.
 - Insert a solid centre or revolving centre into the tailstock spindle.
 - Position the cutting tool tip and tailstock centre together, by rotating the tool post and driving out the tailstock centre.
 - If the cutting tool is below/above the point of the tailstock centre, then you need to raise/lower it until it is in line with the point of the centre.
 - Adjust the screw until the edge of the cutting tool lines up with the point of the centre in the tailstock.
- (Any other relevant answers) (5)
- 3.3
- A – Centre
 - B – Spindle
 - C – Spindle locking lever
 - D – Nut/Screw/Thread
 - E – Handle Wheel
 - F – Frame/Housing/Body
- (6 × 1) (6)
- 3.4
- Speed too high
 - Feed rate too high *FEED*
 - Parting tool above centre height, which causes excessive rubbing
 - Parting tool set too low
 - Lack of coolant
 - Parting tool not sharpened properly
 - Cutting operation is too far from the chuck
 - Parting tool not clamped properly
 - Work not tightly gripped in a chuck
- PARTING TOOL NOT SET 90°* (Any other relevant answers) (Any 5 × 1) (5)
- 3.5
- A wide range of regular and irregular shapes can be held.
 - Work can be set to run concentrically or eccentrically.
 - Considerable gripping power, so that heavy cuts can be taken.
 - There is no loss of accuracy if the chuck becomes worn.
 - The chuck stays accurate, even if it is worn.
 - One can readily do facing and boring.
- * (Any other relevant answers) (Any 4 × 1) (4)

[25]

QUESTION 4

- 4.1
- Clean the table of the machine thoroughly (do not use compressed air).
 - Clean the vice thoroughly.
 - Spread a thin layer of oil on the table surface.
 - Gently place the vice on top of the table.
 - Obtain machine bolts and place the bolts in the slots of the table and of the vice.
 - A washer should be used between the nut and the vice.
 - Tighten the bolts. (Any other relevant answers) (5 x 1) (5)
- 4.2
- | | | | |
|-------|-------------|--|-------------|
| 4.2.1 | Overarm | | |
| 4.2.2 | Knee | | |
| 4.2.3 | Table trips | | |
| 4.2.4 | Saddle | | |
| 4.2.5 | Column | | |
| | | | (5 x 1) (5) |
- 4.3
- | | | | |
|---|------------------------------|--------------------------------|-------------|
| A | Slot cutter | <i>-SIDE & FACE CUTTER</i> | |
| B | T-slot cutter | | |
| C | End-Mill cutter | <i>-SLOT DRILL</i> | |
| D | Dove-tail cutter | | |
| E | Helical cutter/Ripple cutter | | |
| | | | (5 x 1) (5) |
- 4.4
- When manufacturing a work piece, the allowable deviation[✓] from the required size (12 mm) may be bigger (12,00 + 0,02 = 12,02 mm)^{✓✓} or smaller (12,00 - 0,02 = 11,98 mm).^{✓✓} (Use own discretion for the answers) (5)
- 4.5
- Loosen the machine vice and place it in line with movement of the table.[✓]
 Obtain a parallel bar/parallel strip that is about the length as that of the vice jaws (the parallel bar should protrude above the vice jaws).[✓]
 Insert a dial test indicator (DTI) in the magnetic stand onto the machine[✓] with the needle touching the fixed jaw of the vice. Zero the DTI.[✓] Move the table by the handle along the length of the parallel bar. Take note of the reading on the DTI.[✓] Loosen the bolts of the vice and adjust the vice until the vice is parallel to the machine and tighten the machine vice bolts when everything is satisfactory.
- (Any 5 x 1) (5)
[25]
- TOTAL: 100**

