



higher education & training

Department:
Higher Education and Training
REPUBLIC OF SOUTH AFRICA

MARKING GUIDELINE

NATIONAL CERTIFICATE (VOCATIONAL)

**FITTING AND TURNING
NQF LEVEL 2**

04 March 2024

This marking guideline consists of 5 pages.

HIGHER EDUCATION AND TRAINING
PRIVATE BAG X110
2024 -03- - -
PRETORIA 0001
LEFAPHA LA THUTO E KGOLWANE LE THUPELELO

Approved 202403 DHET marking

Guide. No amendments or additions

Must be made on this guide


QUESTION 1

- | | | | | |
|-----|-------|---|---------|-----|
| 1.1 | 1.1.1 | A | | |
| | 1.1.2 | B | | |
| | 1.1.3 | C | | |
| | 1.1.4 | D | | |
| | 1.1.5 | A | | |
| | | | (5 × 1) | (5) |

- 1.2
- It is difficult to control the amount of material being removed.
 - The cutters wear away and have to be replaced.
 - It is difficult to keep the face of the wheel parallel to the edge of the wheel.
 - The tool rest has to be adjusted away from the wheel before dressing the wheel, and then has to be reset in position.
- (Any 3 × 1) (3)

- 1.3
- Straight
 - Cylindrical
 - Flaring cup
 - Dish
 - Saucer
- (5 × 1) (5)

- 1.4
- Loading of the wheel
 - Glazing of the wheel
 - Wheel not running concentrically to the spindle
- (Any 2 × 1) (2)



- 1.6
- M = metric
10 = diameter of the thread
1.25 = pitch of the thread
- (3)

- 1.7
- Spiral-fluted hand taper reamer
Straight-fluted hand taper reamer
- (2)
[25]

QUESTION 2

- 2.1 A – Motor
B – Spindle speed selector
C – Hand feed lever
D – Pillar
E – Base
F – Table (6)

- 2.2 D = ?
S = $25 \times 1\,000 = 25\,000$ mm/min ✓
N = 300

$$S = \pi \times d \times N \checkmark$$

$$D = \frac{S}{\pi \times N} \checkmark$$

$$= \frac{25\,000 \checkmark}{(\pi \times 300) \checkmark}$$

$$= 26,522 \text{ mm} \checkmark$$

Use = 27 mm (6)

- 2.3
- The shape of the workpiece
 - The rigidity of the workpiece
 - The pressure exerted by the drill
 - The ease of locating and removing the clamps
 - The greatest pressure by the clamp without damaging the workpiece (5)

- 2.4
- Width of the key
 - Thickness of the key
 - Diameter of the shaft
 - Length of the key
 - Keyway
 - Hub
- (Any 4 × 2) (8)
[25]

QUESTION 3

- 3.1
- Dead centre
 - Pipe centre
 - Half centre
 - Ball centre
 - Revolving centre
 - Driving centre
- (Any 5 × 1) (5)
- 3.2
- Adhere to all precautionary measures before switching on the machine.
 - Make sure that the spindle rotates at the correct speed.
 - Using the handles, advance the tool until it just touches the circular face and makes a very fine cut on the workpiece.
 - Withdraw the tool by using the compound slide handle.
 - Set the cross slide to zero. Make sure that no backlash is present.
- (5)
- 3.3
- | | |
|-------|---|
| 3.3.1 | A |
| 3.3.2 | D |
| 3.3.3 | H |
| 3.3.4 | E |
| 3.3.5 | I |
| 3.3.6 | F |
- (6 × 1) (6)
- 3.4
- Workpieces can be bored.
 - Workpieces can be rigidly clamped to resist heavy cuts.
 - There are no moving parts that can lose their accuracy with wear.
 - A wide range of regular and irregular components can be held.
 - Work on the end face of the job is possible.
 - Workpieces can be set to run concentrically or eccentrically.
 - Workpieces can be set to a datum surface.
- (Any 4 × 1) (4)
- 3.5
- When loading or unloading a workpiece from the chuck or other holding device, the centre lathe should stand completely still.
 - Observe all precautionary measures and do not wear loose clothing.
 - Brushes or rags should be kept away from moving parts.
 - Chuck keys should not be left in the chuck.
 - Always disconnect, remove or stand clear from handwheels and levers before setting the machine or feed in motion.
 - Never apply a wrench to revolving workpieces or parts.
 - Never adjust the cutting tool while the centre lathe is in motion.
 - Do not attempt to stop the machine by placing your hand on the chuck while the centre lathe is slowing down.
 - Give attention to cutting fluid control before switching the machine on.
- (Any 5 × 1) (5)
- [25]**

QUESTION 4

4.1	4.1.1	A – Column B – Arbor C – Milling cutter D – Overarm E – Table F – Knee G – Base	(7)
	4.1.2	<ul style="list-style-type: none"> • Plain, horizontal milling machine • Universal milling machine • Vertical milling machine • Turret milling machine 	(Any 3 × 1) (3)
4.2		<ul style="list-style-type: none"> • To curb heavy chattering on the cutter • To support the overarm • To support the arbor against bending 	(3 × 2) (6)
4.3		<ul style="list-style-type: none"> • Conventional (up-cut) milling • Climb milling 	(2 × 2) (4)
4.4		<ul style="list-style-type: none"> • Engineer square • Vernier calliper • Machine vice • Plastic hammer • Parallel strips/bars • Clock gauge and stand • Machine clamps • Bolts, nuts and washers to fix the vice and clamps to the table • Spanners for bolts and nuts • Milling cutters 	(Any 5 × 1) (5) [25]
TOTAL:			100