



**higher education
& training**

Department:
Higher Education and Training
REPUBLIC OF SOUTH AFRICA

MARKING GUIDELINE

NATIONAL CERTIFICATE (VOCATIONAL)

**FITTING AND TURNING
NQF LEVEL 3**

9 MARCH 2018


This marking guideline consists of 7 pages.

QUESTION 1: BEARINGS


- 1.1
- Flaking of metal on the outer surface
 - Corrosion on all parts of the bearing
 - Wear on the rolling elements
 - Microcracks on the surfaces of the inner and outer races
 - Grooves on the races and rolling elements
 - Burn holes on the races and rolling elements
- (Any 4 × 1) (4)

- 1.2
- Mounting tube
 - Ballpein hammer
 - Bearing heater
 - Hydraulic press
 - Punch
- (Any 4 × 1) (4)

1.3



Line contact
(roller bearing) ✓



Point contact
(ball bearing) ✓


(2 + 2) (4)

- 1.4
- To keep the bearing lubricant from leaking out
 - To prevent dirt and other contaminants from entering the bearing
- (Any 1 × 1) (1)
[13]

QUESTION 2: COUPLINGS


- 2.1 To join or connect two shafts together for power transmission (cannot be disengaged during operation) (1)

2.2 2.2.1




Parallel misalignment

2.2.2



Angular misalignment

2.2.3



Gap

(3 × 1) (3)

- 2.3
- Misalignment of shafts
 - Using the wrong coupling
 - Incorrect or inadequate lubrication
 - Excessive build-up of dirt may prevent it from adjusting
 - Overloading
 - Incorrect assembly
- (Any 4 × 1) (4)

- 2.4
- Motor rock or soft foot occurs when a motor wobbles✓ due to it not standing on an even surface (the same motion one gets when the legs of a table does not have the same length). It is corrected by inserting shim plates✓ under the side that is causing the problem, thus taking up the gap and stops the movement.
- (Marks to be allocated only if explanation is correct) (2)
[10]

QUESTION 3: BRAKES AND CLUTCHES

- 3.1
- When there is power, the brakes are deactivated✓ and as soon as there is a power failure, the brakes activate.✓ (2)
- 3.2
- Fluid leaks
 - Worn linings
 - Air in the system
 - Scoring of the friction surface (metal to metal contact)
- (Any 3 × 1) (3)
- 3.3
- 1 – Pressure plate
 - 2 – Spring
 - 3 – Release bearing
 - 4 – Flywheel
 - 5 – Clutch plate with asbestos lining or clutch plate
- (5)
[10]

QUESTION 4: BELT DRIVES, CHAIN DRIVES AND GEAR DRIVES


- 4.1 4.1.1 A drive pulley is fitted to the motor which provides the driving motion.
- 4.1.2 A driven pulley is attached to the working part of a machine.
- 4.1.3 An idler pulley keeps the tension of the V-belt constant and/or also increases the arc of contact.
- 4.1.4 The arc of contact is that portion of the pulley that is in contact with the V-belt along its circumference.
- 4.1.5 Centre distance is the distance between the centre of the driving pulley and the centre of the driven pulley.

(5 × 1) (5)

- 4.2
 - Solid
 - Split
 - Idler

(3)

4.3



(Any suitable sketch should be considered) (2)

4.4

ADVANTAGES	DISADVANTAGES
<ul style="list-style-type: none"> • More efficient • Higher speed ratios • More compact • No slippage 	<ul style="list-style-type: none"> • Expensive • Difficult to repair • Requires constant lubrication

(3 + Any 2) (5)

4.5

- 4.5.1 Oil level too low (not correct)
- 4.5.2 Oil level too high causing it to leak from the breather pipe

(2 × 1) (2)

[17]

QUESTION 5: PIPES, PIPE FITTINGS AND VALVES

- 5.1 A – Outside diameter
B – Inside diameter
C – Wall thickness
D – Pipe length (4)
- 5.2 5.2.1 Y-piece
5.2.2 Plug (2 × 1) (2)
- 5.3
- Gate valve
 - Diaphragm valve
 - Ball valve
 - Foot valve
 - Non-return valve
 - Pressure relief valve
 - Safety valve
 - Butterfly valve
- (Any 4 × 1) (4)
[10]

QUESTION 6: CENTRE LATHE

- 6.1
- Wearing loose clothing
 - Wearing jewellery
 - Long hair without a hairnet
 - Workpiece not clamped securely
 - Not wearing goggles
 - Leaving the chuck wrench in the chuck
 - Making adjustments while the machine is on or running
 - Working on the lathe without proper machine guards or chip shields in place
 - Dirty/Wet floor
- (Any 5 × 1) (5)
- 6.2 D = 60 mm = 60/1 000 = 0,06 m
- S = 30 m/min
- $S = \pi \times D \times N$
- $N = S/\pi \times D$
 $= 30/\pi \times 0,06 \checkmark \checkmark$
 $= \underline{159,155 \text{ r/min}} \checkmark$ (3)

- 6.3
- Place a centre in the headstock spindle or tailstock spindle.
 - By means of a combined movement between the cross slide and compound slide, move the cutting tool point closer to the centre point.
 - Adjust the height of the cutting tool until the cutting tool is at centre height to the centre point (spacers or shim plates may be used).
 - Tighten the cam lock handle and check the centre height again.
 - Position the tool post correctly and then tighten it to prevent it from moving.
- (5)

6.4

ADVANTAGES	DISADVANTAGES
<ul style="list-style-type: none"> • The chuck can hold a wide range of hexagonal and cylindrical workpieces. 	<ul style="list-style-type: none"> • The chuck becomes inaccurate as the jaws become worn.
<ul style="list-style-type: none"> • Jaws are available for internal and external work. 	<ul style="list-style-type: none"> • The chuck can only hold hexagonal and cylindrical workpieces.
<ul style="list-style-type: none"> • Work can be done on the end face of the workpiece. 	<ul style="list-style-type: none"> • It is not possible to correct any run out.
<ul style="list-style-type: none"> • It is easy to mount the workpiece. 	<ul style="list-style-type: none"> • The chuck is heavy to handle.
	<ul style="list-style-type: none"> • The gripping power of the chuck can damage the workpiece.
	<ul style="list-style-type: none"> • Concentric accuracy is limited when the workpiece is reversed.

(Any 2 + Any 3) (5)

- 6.5 The coolant keeps the cutter and the workpiece cool. It also washes away the cutting chips or shavings.
- (2)
[20]

QUESTION 7: MILLING MACHINE

- 7.1
- Perform a routine maintenance check (all oil levels, etc.).
 - Lubricate the moving parts.
 - Check that the machine guards are in place.
 - Choose the correct cutter to machine the workpiece.
- (4)
- 7.2
- Shape of the workpiece
 - Pressure by the clamp
 - Rigidity of the workpiece
 - Pressure exerted by the milling cutter
 - Ease of locating and removing the clamps
- (5)

- 7.3 Indexing = $\frac{24}{8}$
= 3 holes on a 24-hole circle (2)
- 7.4 $S = \pi \times D \times N$
 $N = S/\pi \times D$
= $25/\pi \times 0,012$ ✓✓
= 663,146 r/min ✓
- $f = f_t \times T \times N$
= $0,18 \times 2 \times 663,146$ ✓✓
= 238,732 mm/min ✓ (6)
- 7.5 It means that the required measurement to which the workpiece may be machined to is not allowed to be above or under the actual size by more than 0,02 mm. (2)
- 7.6 Bearing seizure (1)
[20]
- TOTAL: 100**